| - - | EATHER CONSENT DECREE ATER TESTING FORM | Page/_ of3 |
|---|---|--|
| Sewershed: PATAPSCO | Company: Savin Engineers | Date: <u>9-30-09</u> |
| Test to be Performed: Smoke: X Dyed Water: | Ground Condition: Dry: X Damp: Wet: | Supervisor: Joe Mirabito |
| Manhole ID: S3/MI_ 022 M4 | Test ID: 5/04/-1/6 | Notifications Made: (Residents, Fire, 311) |
| S31M1 SLOWS 617 515 52 617 603 607 605 5033 601 619 617 603 607 605 5033 601 | 2≦01 | \$31M1_021N \$31M1_014MH |

| CITY OF BALTIMORE WET WEATHER CONSENT D SMOKE AND DYED WATER TESTING FORM | | | | | _ | E | Page 2 of 3 | | |
|---|-------------------|----------------------|--------------------------------------|---------------------------------------|--------------|--|------------------------|-------------------|--------|
| Sewer | shed: <u>PATA</u> | PSCO | | Compan | y: <u>SA</u> | VIN | | Date: <u>9/30</u> | /09 |
| Test to be Performed: Smoke: X Dyed Water: | | | Ground Condition: Dry: X Damp: Wet: | | | | Supervisor: <u>JAM</u> | | |
| Manhole ID: S31M1_022MH | | Test ID: S1041 - 116 | | | | Notifications Made: X (Residents, Fire, 311) | | | |
| Field Sketch: (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers) | | | | | | | | | |
| Defect | | - | | Source | | | Drainage | | Photo |
| No. | | Address | | Type | Location | Sector | Area | Severity | Number |
| 1 | 505 CHERR | RY HILL RD |) | 3 | 7 | 2 | 0 | 4 | P01 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | OBSERV | ATION | CODES | ļ | | |
| | Source Type | Location | Sector | Severity | | Source Type | Location | | |
| 01 | Main Sewer | Paved Concrete | Public | No Smoke | 10 | MH Frame Seal | Non-Paved | | |
| | Service Line | Paved Asphalt | Private | Trace | | Storm Drain | Field/Woods | | |
| | Cleanout | Paved Other | | Moderate | | Catch Basin/Inlet | | | |
| | Downspout | Driveway | | Major | | Storm Manhole | Golf Course | | |
| | Area Drain | Sidewalk | | , , , , , , , , , , , , , , , , , , , | | Storm Ditch | Other | | |
| | Driveway Drain | Curb | | | | Excavation | | | |
| | Stairwell Drain | Yard- Front | | | | Other | | | |
| | Foundation Drain | Yard-Back | | | | | | | |
| 09 | Building Interior | Yard- Side | | | | | | | |

| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page <u>3</u> of <u>3</u> | |
|---|----------------------------|--|
| Sewershed: PATAPSCO | Company: Savin Engineers | Date: <u>9/30/09</u> |
| Test to be Performed: | Ground Condition: | Supervisor: Joe Mirabito |
| Smoke: X Dyed Water: | Dry: X Damp: Wet: | |
| Manhole ID: <u>\$31M1_022MH</u> | Test ID: <u>\$1041-116</u> | Notifications Made: X (Residents, Fire, 311) |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



S1041-116-OB01-P01